



Product Bulletin

<h2>Product Bulletin</h2>	<h3>Replacement of 4000 Series 4m wiring harness (bespoke customer option)</h3>
Market	Electric power
Engine Platforms	All 4000 Series variants
Engine Build Lists	Please see appendix for build lists affected
Details of Change What is the Change	<p>In line with continuous improvement Perkins will no longer supply the 4m wiring harness extension, part number 680/196, from 31st May 2022.</p>  <p>Perkins will continue to supply the ECM connector, 680/200, which will allow customers to wire an extended harness if required.</p> 
Reason for Change Why was the change made?	Supply of connector 680/200 allows greater flexibility where harness length can be varied to support customer requirements.
OEM Effect What is the effect on Form, Fit or Function?	<p>The build lists with the 4 metre harness will be made obsolete.</p> <p>Customers are requested to select a suitable replacement build list with the ECM connector 680/200. Please see appendix</p>
Impact on Aftermarket	None
Availability	Timeline: <ul style="list-style-type: none"> • Last orders May 31st 2022 • Last engines shipped from the factory September 30th 2022

Product Bulletin

Appendix - Current build lists affected with suggested alternative lists

Current list number	Description	Suggested replacement future list numbers; these lists don't have a wiring harness but they do have ECM connectors 680/200
DGBR1126	4016TAG2A 1500RPM EU	DGBR1737
DGDF1343	4006-23TAG3A 1500RPM EP	DGDF1736
DGWR1389	4016-61TRG2 1500RPM EU	DGWR1738
DGXR1034	4016-61TRG 1500RPM EU	DGXR1740
DGWR1714	4016-61TRG2 1500RPM EU	DGWR1739
DGAH1339	4008TAG1A 1500RPM EU	DGAH1741