

# engine news

product support information for industrial engines

01 August 2022

i09577851

## Improved Engine Oil Pressure Switch

### Industrial Engine:

**1104C-44 (RE)**  
**400F (EG; EJ; EK)**  
**1104D(MECH) (NK; NL; NM)**  
**1106 (PP; PR; PU)**  
**402D-403D-404D (GG; GH; GJ; GK; GL; GN; GP; GR; GS)**  
**402J-05 (IG)**  
**403A (GT; GU; GV)**  
**403F-15 (EL)**  
**403J-07 (IH)**  
**403J-11 (IJ)**  
**403J-17 (IS)**  
**403J-17T (IF)**  
**403J-E17T (IW)**  
**404J-22 (IN)**  
**404J-E22T (IQ)**  
**404J-E22TA (IR)**  
**904D-E36TA (FT)**  
**904J-E28T (FL)**  
**904J-E28TA (FM)**  
**904J-E36TA (FW; FX)**

An improved engine oil pressure switch has been introduced. The new engine oil pressure switch has improvements to prevent potential internal leaks.

### **WARNING**

Do not operate or work on this product unless you have read and understood the instructions and warnings in the relevant Operation and Maintenance Manuals and relevant service literature. Failure to follow the instructions or heed the warnings could result in injury or death. Proper care is your responsibility.

Refer to Table 1 for the parts information.

Table 1

Part Number	Date Stamp for Improved Part
T421762	34/21
T431758	242/21
185246240	34/21
U85246310	34/21
185246280	34/21
U85246210	34/21
2848A051	34/21
2848A071	34/21

